

Standard Operating Procedure for Resolving ALARM_7033 on Cisco-Access-Kolkata-WB-112

Node: Cisco-Access-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_7033

Description

ALARM_7033: Critical - The Cisco-Access-Kolkata-WB-112 access switch has encountered a critical hardware failure, resulting in a system crash.

Potential Root Causes

Cause	Probability
Power Supply Unit (PSU) Failure	High
Fan Failure	Medium
Overheating	Low

Diagnostic Commands

```
show environment all
show power inline all
show fan all
show temperature all
```

Resolution Steps

Step 1: {'Step': 'Power Cycle the Switch', 'Action': 'Switch# reload', 'Note': 'This action may resolve the issue if it is caused by a temporary software glitch or minor hardware issue.'}

Step 2: {'Step': 'Replace the PSU', 'Action': 'Use the spare PSU and replace the faulty one.', 'Note': 'When replacing the PSU, ensure that it is properly seated and secured to the switch.'}

Step 3: {'Step': 'Replace the Fan', 'Action': 'Use the spare fan and replace the faulty one.', 'Note': 'When replacing the fan, ensure that it is properly seated and secured to the switch.'}

Step 4: {'Step': 'Verify the Temperature', 'Action': 'Use the "show temperature all" command to verify that the temperature is within the acceptable range.', 'Note': 'If the temperature is still high, consider relocating the switch to a cooler environment.'}

Post-Check Verification

```
show environment all
show power inline all
```

```
show fan all  
show temperature all
```