

Standard Operating Procedure for Cisco Access Switch ALARM_8415

Node: Cisco-Access-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_8415

Description

Minor alarm indicating a potential issue with the Access Switch Node Cisco-Access-Kolkata-WB-112

Potential Root Causes

Cause	Probability
Incorrect VLAN configuration	High
Switch stack issue due to synchronization failure	Medium
Interface malfunction due to faulty optics or cabling	Low

Diagnostic Commands

```
show vlan brief
show switch stack
show int status
show log | include ALARM_8415
```

Resolution Steps

- Step 1: {'Step': '1', 'Action': "Verify the VLAN configuration using the command 'show vlan brief'", 'CLI_Commands': 'show vlan brief'}
- Step 2: {'Step': '2', 'Action': "Check the switch stack status using the command 'show switch stack'", 'CLI_Commands': 'show switch stack'}
- Step 3: {'Step': '3', 'Action': "Replace faulty optics or cables, and re-check the interface status using 'show int status'", 'CLI_Commands': 'show int status'}
- Step 4: {'Step': '4', 'Action': "Restart the switch if the issue persists, and verify the fix using 'show log | include ALARM_8415'", 'CLI_Commands': 'show log | include ALARM_8415'}

Post-Check Verification

```
show log | include ALARM_8415
show int status
```