

SOP: Troubleshooting ALARM_7115 on Cisco-Access-Kolkata-WB-124

Node: Cisco-Access-Kolkata-WB-124 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_7115

Description

ALARM_7115 on Cisco-Access-Kolkata-WB-124 indicates a major issue with the access switch. This SOP outlines the steps to troubleshoot and resolve the issue.

Potential Root Causes

Cause	Probability
Interface flapping due to cable issues	High
Misconfigured interface settings	Medium
Hardware failure on the switch	Low

Diagnostic Commands

```
show interface status
show interface GigabitEthernet 0/1 transceiver
show log | include ALARM_7115
show run | include interface GigabitEthernet 0/1
```

Resolution Steps

- Step 1: {'Step': "1. Check the interface status using 'show interface status'", 'Action': "Verify if the interface is up or down. If down, proceed to step 2."}
- Step 2: {'Step': "2. Inspect the transceiver using 'show interface GigabitEthernet 0/1 transceiver'", 'Action': "Verify if the transceiver is functioning properly. If not, replace it with a new one."}
- Step 3: {'Step': "3. Check the interface configuration using 'show run | include interface GigabitEthernet 0/1'", 'Action': "Verify if the interface configuration is correct. If not, correct it."}
- Step 4: {'Step': "4. Check the logs using 'show log | include ALARM_7115'", 'Action': "Verify if there are any logs related to the alarm. If yes, investigate further."}
- Step 5: {'Step': "5. Replace the switch if hardware failure is suspected", 'Action': "Replace the switch with a new one and verify if the alarm is resolved."}

Post-Check Verification

```
show interface status
```

```
show interface GigabitEthernet 0/1 transceiver
```