

Cisco Access Switch Alarm Resolution SOP - ALARM_8926

Node: Cisco-Access-Kolkata-WB-124 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_8926

Description

This SOP outlines the procedures for resolving the warning alarm ALARM_8926 on the Cisco Access Switch Node ID: Cisco-Access-Kolkata-WB-124.

Potential Root Causes

Cause	Probability
High CPU Utilization due to software issues	High
Misconfigured QoS settings	Medium
Inadequate switch memory resources	Low

Diagnostic Commands

```
show processes cpu | include System
show qos policy-map all
show memory | include Total
```

Resolution Steps

- Step 1: {'Step': '1', 'Action': 'Clear the CPU utilization alarm', 'CLI_Command': 'clear cpu-process cpu-utilization'}
- Step 2: {'Step': '2', 'Action': 'Verify that the QoS policy is correctly configured', 'CLI_Command': 'show running-config | include qos policy-map'}
- Step 3: {'Step': '3', 'Action': 'Adjust memory resources if necessary', 'CLI_Command': 'memory adjust size '}
- Step 4: {'Step': '4', 'Action': 'Verify that the issue is resolved', 'CLI_Command': 'show processes cpu | include System'}

Post-Check Verification

```
show processes cpu | exclude System
show qos policy-map all
show memory | include Total
```