

SOP: Resolving Critical Alarm ALARM_2906 on Cisco Access Switch (Node ID: Cisco-Access-Kolkata-WB-126)

Node: Cisco-Access-Kolkata-WB-126 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_2906

Description

This SOP outlines the steps to diagnose and resolve critical alarm ALARM_2906 on Cisco Access Switch (Node ID: Cisco-Access-Kolkata-WB-126).

Potential Root Causes

Cause	Probability
Incorrect configuration of VLANs or VLAN trunking protocols	High
Hardware or software failure in the switch	Medium
Cabling or connectivity issues between switches	Low

Diagnostic Commands

```
show spanning-tree vlan 1
show interface status
show interface trunk
show vlan
show mac address-table
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration and trunking protocols', 'Action': 'Use show vlan and show interface trunk commands to verify VLAN configuration and trunking protocols.'}
- Step 2: {'Step': 'Check for hardware or software failure', 'Action': 'Use show system resource and show version commands to check for hardware or software failure.'}
- Step 3: {'Step': 'Check for cabling or connectivity issues', 'Action': 'Use show interface status command to check for cabling or connectivity issues between switches.'}
- Step 4: {'Step': 'Correct configuration or hardware issues', 'Action': 'Use appropriate CLI commands to correct configuration or hardware issues.'}

Post-Check Verification

```
show spanning-tree vlan 1
show interface status
show interface trunk
show vlan
show mac address-table
```