

Cisco Access Switch Standard Operating Procedure (SOP) for ALARM_4532

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_4532

Description

This SOP outlines the steps to diagnose and resolve a Major alarm (ALARM_4532) on the Cisco Access Switch (Node ID: Cisco-Access-Mumbai-MH-38).

Potential Root Causes

Cause	Probability
High CPU utilization due to stuck CPU process	High
Misconfigured VLAN or port settings	Medium
Hardware failure or malfunction	Low

Diagnostic Commands

```
show processes cpu | include Stuck
show system resources
show vlan
show interface
```

Resolution Steps

- Step 1: {'Step': '1. Check for stuck CPU process', 'Action': "Run 'show processes cpu | include Stuck' to identify stuck processes", 'CLI_Command': 'clear process cpu Stuck'}
- Step 2: {'Step': '2. Verify VLAN and port configurations', 'Action': "Run 'show vlan' and 'show interface' to verify VLAN and port settings", 'CLI_Command': 'no switchport mode access'}
- Step 3: {'Step': '3. Perform hardware reset', 'Action': 'Perform a hardware reset to clear any hardware-related issues', 'CLI_Command': 'power-off'}

Post-Check Verification

```
show processes cpu | include Stuck
show system resources
show vlan
show interface
```