

Cisco Access Switch Alarm SOP - ALARM_7546

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_7546

Description

Warning: Potential issue with Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-38

Potential Root Causes

Cause	Probability
Misconfigured VLAN	High
Switch software issue	Medium
Environmental issue (Temperature, Power)	Low

Diagnostic Commands

```
show spanning-tree vlan
show interfaces status
show vlan
show tech-support
```

Resolution Steps

Step 1: {'Step': '1. Check VLAN configuration', 'Action': 'Verify VLAN configuration using the show vlan command.', 'CLI_Command': 'show vlan'}

Step 2: {'Step': '2. Check spanning tree configuration', 'Action': 'Verify spanning tree configuration using the show spanning-tree vlan command.', 'CLI_Command': 'show spanning-tree vlan'}

Step 3: {'Step': '3. Check switch software', 'Action': 'Verify switch software version and look for any software issues.', 'CLI_Command': 'show version'}

Step 4: {'Step': '4. Check environmental issues', 'Action': 'Verify environment conditions using the show environment command.', 'CLI_Command': 'show environment'}

Post-Check Verification

```
show vlan
show spanning-tree vlan
show interfaces status
show version
```