

ALARM_9900: Cisco Access Switch Mumbai MH-38

High Priority Alarm SOP

Node: Cisco-Access-Mumbai-MH-38 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_9900

Description

Alarm Code: ALARM_9900, Severity: Major, Vendor: Cisco, Role: Access Switch, Node ID: Cisco-Access-Mumbai-MH-38

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Software Bug	Medium
Hardware Failure	Low

Diagnostic Commands

```
show processes cpu
show system resources
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Run show processes cpu command to check CPU utilization.', 'CLI_Command': 'show processes cpu'}
- Step 2: {'Step': '2. Check System Resources', 'Action': 'Run show system resources command to check system resources.', 'CLI_Command': 'show system resources'}
- Step 3: {'Step': '3. Run Tech Support', 'Action': 'Run show tech-support command to gather system information.', 'CLI_Command': 'show tech-support'}
- Step 4: {'Step': '4. Upgrade Firmware (if necessary)', 'Action': 'Upgrade firmware if the issue is caused by a software bug.', 'CLI_Command': 'firmware upgrade'}
- Step 5: {'Step': '5. Replace Hardware (if necessary)', 'Action': 'Replace hardware if the issue is caused by a hardware failure.', 'CLI_Command': ''}

Post-Check Verification

```
show processes cpu
show system resources
```

show tech-support