

SOP: Resolving Major Alarm ALARM_2445 on Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-40

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_2445

Description

This SOP outlines the steps to resolve the Major Alarm ALARM_2445 on the Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-40. The alarm is triggered due to a critical issue affecting the network.

Potential Root Causes

Cause	Probability
Layer 2 Forwarding Issue	High
Spanning Tree Protocol (STP) Configuration Issue	Medium
Switch Hardware Failure	Low

Diagnostic Commands

```
show spanning-tree
show interfaces
show mac address-table
show switch hardware
debug spanning-tree
```

Resolution Steps

Step 1: {'Step': 'Step 1: Verify STP Configuration', 'Action': "Verify the STP configuration on the switch using the command 'show spanning-tree'. If any discrepancies are found, correct the configuration.", 'CLI_Command': 'configure terminal | spanning-tree mode'}

Step 2: {'Step': 'Step 2: Check for Forwarding Issues', 'Action': "Verify the forwarding table on the switch using the command 'show mac address-table'. If any issues are found, clear the forwarding table using the command 'clear mac address-table dynamic'.", 'CLI_Command': 'clear mac address-table dynamic'}

Step 3: {'Step': 'Step 3: Investigate Hardware Issues', 'Action': "Verify the switch hardware status using the command 'show switch hardware'. If any hardware issues are found, replace the faulty hardware.", 'CLI_Command': 'show switch hardware'}

Step 4: {'Step': 'Step 4: Reboot the Switch', 'Action': 'Reboot the switch to ensure all changes take effect.', 'CLI_Command': 'reload'}

Post-Check Verification

```
show spanning-tree
show interfaces
show mac address-table
show switch hardware
show version
```