

Cisco-Access-Mumbai-MH-40 Alarm Handling: ALARM_4222 (Warning)

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_4222

Description

Alarm ALARM_4222 is triggered on Cisco-Access-Mumbai-MH-40 Access Switch due to a potential issue affecting network performance.

Potential Root Causes

Cause	Probability
Misconfigured VLANs on the Access Switch	High
Spanning Tree Protocol (STP) topology changes	Medium
Hardware or software issues on the Access Switch	Low

Diagnostic Commands

```
show vlan
show spanning-tree
show interface status
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration and correct if necessary', 'Action': "Use the 'show vlan' command to verify VLAN configuration. If VLANs are misconfigured, correct the configuration using the 'vlan' command."}
- Step 2: {'Step': 'Verify STP topology', 'Action': "Use the 'show spanning-tree' command to verify STP topology. If topology has changed, investigate and correct if necessary."}
- Step 3: {'Step': 'Restart the Access Switch', 'Action': "Perform a soft reset of the Access Switch using the 'reload' command to restart the device."}
- Step 4: {'Step': 'Upgrade or replace hardware/software', 'Action': "If hardware or software issues are suspected, upgrade or replace the affected components using the 'upgrade' or 'install' command."}

Post-Check Verification

```
show vlan
show spanning-tree
```

```
show interface status
show tech-support
```