

Standard Operating Procedure for Resolving Cisco Access Switch Alarm ALARM_5157 in Mumbai Location

Node: Cisco-Access-Mumbai-MH-40 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_5157

Description

This SOP outlines the steps to diagnose and resolve the Cisco access switch alarm ALARM_5157, which indicates a major issue in the Mumbai location.

Potential Root Causes

Cause	Probability
Faulty or misconfigured Power Supply Unit (PSU)	High
Overheating of Switching Module	Medium
Software or firmware issues with the switch	Low

Diagnostic Commands

```
show power supply
show environment temperature
show system resources
show version
debug platform software switch
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch to reset the system', 'Action': "use the 'reload' command to power cycle the switch"}
- Step 2: {'Step': 'Replace the faulty PSU', 'Action': "use the 'no power supply' command to disable the PSU and then physically replace it"}
- Step 3: {'Step': 'Verify the temperature of the switching module', 'Action': "use the 'show environment temperature' command to check the temperature"}
- Step 4: {'Step': 'Update the switch software or firmware to the latest version', 'Action': "use the 'copy tftp: flash:' command to update the software or firmware"}
- Step 5: {'Step': 'Verify the system resources are within normal limits', 'Action': "use the 'show system resources' command to check the system resources"}

Post-Check Verification

```
show power supply
show environment temperature
show system resources
show version
```