

Cisco-Access-Mumbai-MH-52 Alarm SOP:

ALARM_6668

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_6668

Description

Warning: The Cisco-Access-Mumbai-MH-52 access switch has detected a potential issue related to interface configuration.

Potential Root Causes

Cause	Probability
Interface misconfiguration	High
Cable or connector issues	Medium
Switch software malfunction	Low

Diagnostic Commands

```
show interface status
show interface brief
show run | include interface
debug interface
```

Resolution Steps

- Step 1: {'Step': 'Verify interface configuration', 'Action': "Run 'show interface status' and 'show interface brief' commands to verify interface status and configuration.", 'CLI_Command': 'show interface status'}
- Step 2: {'Step': 'Check for cable or connector issues', 'Action': 'Inspect the interface cables and connectors for any physical damage or corrosion.', 'CLI_Command': ''}
- Step 3: {'Step': 'Reset the interface', 'Action': "Run 'no shutdown' command on the problematic interface to reset it.", 'CLI_Command': 'interface \nshutdown\nno shutdown'}
- Step 4: {'Step': 'Reload the switch', 'Action': "Run 'reload' command to reboot the switch.", 'CLI_Command': 'reload'}

Post-Check Verification

```
show interface status
show interface brief
```

```
show run | include interface
```