

Cisco Access Switch Alarm SOP - ALARM_7107

Node: Cisco-Access-Mumbai-MH-52 | **Vendor:** Cisco | **Severity:** Warning | **Alarm Code:** ALARM_7107

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7107 (Warning) on Cisco Access Switch Node ID: Cisco-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
Port link flapping or misconfiguration	High
Hardware issue with the switch or port	Medium
Software issue or bug	Low

Diagnostic Commands

```
show interface status
show interface GigabitEthernet 0/1 (or affected port)
debug interface GigabitEthernet 0/1 (or affected port)
show logging | include ALARM_7107
```

Resolution Steps

- Step 1: {'Step': '1. Check the interface status and configuration', 'Action': "Use the 'show interface status' command to verify the interface status and configuration."}
- Step 2: {'Step': '2. Verify port settings', 'Action': "Use the 'show interface GigabitEthernet 0/1 (or affected port)' command to verify port settings."}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': "Use the 'show inventory' command to check for any hardware issues."}
- Step 4: {'Step': '4. Check for software issues', 'Action': "Use the 'show version' command to verify the software version and check for any known issues."}
- Step 5: {'Step': '5. Disable and re-enable the interface', 'Action': "Use the 'shutdown' and 'no shutdown' commands to disable and re-enable the interface."}

Post-Check Verification

```
show interface status
show interface GigabitEthernet 0/1 (or affected port)
```

```
show logging | include ALARM_7107
```