

Cisco PE Router Alarm Resolution SOP

(ALARM_4517)

Node: Cisco-PE-Chennai-TN-88 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_4517

Description

This SOP outlines the steps to diagnose and resolve the ALARM_4517 on Cisco PE Router Node ID: Cisco-PE-Chennai-TN-88.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Memory Leak	Medium
Routing Protocol Issues	Low

Diagnostic Commands

```
show processes cpu | exclude System
show memory
show ip bgp summary
debug ip bgp
```

Resolution Steps

- Step 1: {'Step': '1', 'Action': 'Check CPU Utilization and Memory Usage', 'CLI_Commands': 'show processes cpu | exclude System, show memory'}
- Step 2: {'Step': '2', 'Action': 'Clear Memory Leaks (if detected)', 'CLI_Commands': 'clear memory'}
- Step 3: {'Step': '3', 'Action': 'Verify Routing Protocol Stability', 'CLI_Commands': 'show ip bgp summary'}
- Step 4: {'Step': '4', 'Action': 'Restart BGP Process (if necessary)', 'CLI_Commands': 'reload bgp'}

Post-Check Verification

```
show processes cpu | exclude System
show memory
show ip bgp summary
debug ip bgp
```