

Standard Operating Procedure for Resolving Alarm

ALARM_4960 on Cisco-PE-Chennai-TN-88

Node: Cisco-PE-Chennai-TN-88 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_4960

Description

This SOP outlines the steps to diagnose and resolve the Minor alarm ALARM_4960 on Cisco-PE-Chennai-TN-88, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Misconfigured BGP session	Medium
Interface issue on PE router	High
Routing policy mismatch	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors summary
show interfaces status
show ip route detail
```

Resolution Steps

- Step 1: {'Step': '1. Verify BGP session configuration', 'Action': 'Check for any configuration changes or errors using the command "show running-config"}
- Step 2: {'Step': '2. Check interface status', 'Action': 'Use the command "show interfaces status" to verify interface up/down status'}
- Step 3: {'Step': '3. Check BGP session status', 'Action': 'Use the command "show ip bgp neighbors summary" to verify BGP session status'}
- Step 4: {'Step': '4. Adjust routing policy (if necessary)', 'Action': 'Use the command "configure terminal" followed by "route-map permit " to adjust routing policy'}

Post-Check Verification

```
show ip bgp summary
show ip bgp neighbors summary
show interfaces status
```

```
show ip route detail
```