

Cisco Provider Edge Router (PE) Alarm SOP: ALARM_7908

Node: Cisco-PE-Delhi-NCR-33 | **Vendor:** Cisco | **Severity:** Critical | **Alarm Code:** ALARM_7908

Description

Critical alarm on Cisco-PE-Delhi-NCR-33 indicating a severe network disruption. Immediate attention is required to isolate and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfigured Routing	Low

Diagnostic Commands

```
show version
show inventory
show log | include ALARM_7908
debug ip routing
```

Resolution Steps

- Step 1: {'Step': 'Isolate the affected network segment', 'Action': "Use the 'show ip interface brief' command to identify affected interfaces."}
- Step 2: {'Step': 'Power cycle the device', 'Action': "Use the 'power off' and 'power on' commands to restart the router."}
- Step 3: {'Step': 'Verify routing configuration', 'Action': "Use the 'show running-config' command to review routing configuration."}
- Step 4: {'Step': 'Apply software patch (if applicable)', 'Action': "Use the 'copy tftp:' command to apply the latest software patch."}
- Step 5: {'Step': 'Engage vendor support (if necessary)', 'Action': 'Contact Cisco TAC for further assistance and guidance.'}

Post-Check Verification

```
show ip interface brief
```

```
show ip routing table  
show log | include ALARM_7908
```