

Cisco PE Router Alarm SOP: ALARM_1169 (Minor)

Node: Cisco-PE-Kolkata-WB-107 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_1169

Description

This SOP outlines the steps to diagnose and resolve a Minor alarm on the Cisco Provider Edge Router (Node ID: Cisco-PE-Kolkata-WB-107) triggered by Alarm Code ALARM_1169.

Potential Root Causes

Cause	Probability
Misconfigured BGP session	Medium
Interface flap	Medium
Routing protocol issue	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors
show interfaces status
show ip ospf interface
show ip eigrp interface
```

Resolution Steps

Step 1: {'Step': 'Verify BGP session status', 'Action': 'Run `show ip bgp summary` command to verify BGP session status.'}

Step 2: {'Step': 'Check interface status', 'Action': 'Run `show interfaces status` command to verify interface status.'}

Step 3: {'Step': 'Clear BGP session', 'Action': 'Run `clear ip bgp \*` command to clear BGP session.'}

Step 4: {'Step': 'Verify routing protocol status', 'Action': 'Run `show ip ospf interface` or `show ip eigrp interface` command to verify routing protocol status.'}

Post-Check Verification

```
show ip bgp summary
show interfaces status
show ip ospf interface
show ip eigrp interface
```