

SOP - Resolving Major Alarm ALARM_7143 on Cisco-PE-Kolkata-WB-112

Node: Cisco-PE-Kolkata-WB-112 | **Vendor:** Cisco | **Severity:** Major | **Alarm Code:** ALARM_7143

Description

A major alarm ALARM_7143 has been triggered on Cisco-PE-Kolkata-WB-112, a Provider Edge Router (PE) device. This SOP outlines the steps to diagnose, resolve, and verify the fix for this critical issue.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
BGP Session Failure	Medium
Routing Information Protocol (RIP) Misconfiguration	Low

Diagnostic Commands

```
show processes cpu sorted
show ip bgp summary
show ip rip database
```

Resolution Steps

- Step 1: {'Step': 'Check CPU Utilization', 'Description': 'Verify if the CPU utilization is high.', 'CLI_Commands': ['show processes cpu sorted', 'show processes memory'], 'Actions': ['Adjust the CPU-intensive processes as necessary.', 'Consider adding more memory to the device if possible.']}
- Step 2: {'Step': 'Verify BGP Session Status', 'Description': 'Check the status of the BGP sessions.', 'CLI_Commands': ['show ip bgp summary', 'show ip bgp neighbors'], 'Actions': ['Verify that all BGP sessions are established and stable.', 'Check the BGP configuration for any errors or inconsistencies.']}
- Step 3: {'Step': 'Verify RIP Configuration', 'Description': 'Verify the RIP configuration.', 'CLI_Commands': ['show ip rip database', 'show running-config | include rip'], 'Actions': ['Verify that the RIP configuration is correct and consistent.', 'Check for any RIP-related errors or inconsistencies.']}

Post-Check Verification

```
show ip bgp summary
show ip rip database
show processes cpu sorted
```