

Standard Operating Procedure: Resolving Minor Alarm ALARM_9203 on Cisco-PE-Kolkata-WB-124

Node: Cisco-PE-Kolkata-WB-124 | **Vendor:** Cisco | **Severity:** Minor | **Alarm Code:** ALARM_9203

Description

Alarm ALARM_9203 indicates a minor issue with the Cisco-PE-Kolkata-WB-124 Provider Edge Router. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfiguration of BGP neighbor	Medium
Interface flapping	Low
Software bug	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors [neighbor_ip]
show int status | include flapping
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP configuration', 'Action': 'Run show ip bgp neighbor [neighbor_ip] command to check BGP state and verify configuration.'}
- Step 2: {'Step': 'Check interface status', 'Action': 'Run show int status command to check interface status and troubleshoot any issues.'}
- Step 3: {'Step': 'Reboot the router (if software bug suspected)', 'Action': 'Run reload command to reboot the router and isolate the issue.'}
- Step 4: {'Step': 'Clear BGP session', 'Action': 'Run clear ip bgp * command to clear the BGP session.'}

Post-Check Verification

```
show ip bgp summary
show ip bgp neighbors [neighbor_ip]
show int status
```