

Ericsson Access Switch - ALARM_1287 Resolution SOP

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_1287

Description

Alarm Code: ALARM_1287 - Severity: Critical - Node ID: Ericsson-Access-Bangalore-KA-64. This SOP outlines the steps to diagnose and resolve the alarm.

Potential Root Causes

Cause	Probability
Hardware failure in the Access Switch	High
Software issue with the Access Switch	Medium
Network congestion causing packet loss	Low

Diagnostic Commands

```
show tech support info
show alarm information
show interface status
show system resources
```

Resolution Steps

- Step 1: {'Step': '1. Restart the Access Switch', 'Description': "Enter the command 'system restart' to restart the Access Switch.", 'CLI_Command': 'system restart\n'}
- Step 2: {'Step': '2. Run a system software check', 'Description': "Enter the command 'system software check' to check for any software issues.", 'CLI_Command': 'system software check\n'}
- Step 3: {'Step': '3. Check for hardware issues', 'Description': "Enter the command 'show tech support info' to check for any hardware issues.", 'CLI_Command': 'show tech support info\n'}

Post-Check Verification

```
show alarm information
show interface status
show system resources
```