

Ericsson Access Switch - ALARM_3734 SOP

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_3734

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3734 on Ericsson Access Switch Node ID: Ericsson-Access-Bangalore-KA-64.

Potential Root Causes

Cause	Probability
Failed or faulty Ethernet card	High
Incorrect configuration	Medium
Hardware failure in the switch	Low

Diagnostic Commands

```
show system eth-card status
show system eth-card statistics
show system config
show system log | include ALARM_3734
```

Resolution Steps

- Step 1: {'Step': 'Check the system log for recent errors', 'Action': 'show system log | include ALARM_3734'}
- Step 2: {'Step': 'Verify the Ethernet card status', 'Action': 'show system eth-card status'}
- Step 3: {'Step': 'Check the Ethernet card statistics', 'Action': 'show system eth-card statistics'}
- Step 4: {'Step': 'Reboot the switch to clear the alarm', 'Action': 'reboot'}
- Step 5: {'Step': 'Reconfigure the switch if required', 'Action': 'show system config | include '}

Post-Check Verification

```
show system eth-card status
show system log | include ALARM_3734
show system config
```