

Ericsson-Access-Bangalore-KA-64: ALARM_4069

Critical Alarm Resolution SOP

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_4069

Description

This SOP outlines the steps to diagnose and resolve the Ericsson Access Switch ALARM_4069, a critical alarm indicating a hardware fault.

Potential Root Causes

Cause	Probability
Failed Power Supply Unit (PSU)	High
Faulty Fan Module	Medium
Overheating CPU	Low

Diagnostic Commands

```
show system status
show system alarms
show power supply status
show fan status
show cpu temperature
```

Resolution Steps

Step 1: {'Step': 'Replace failed PSU', 'Action': 'Power down the node, replace the PSU with a spare, and power on the node.'}

Step 2: {'Step': 'Replace faulty Fan Module', 'Action': 'Power down the node, replace the faulty fan module with a spare, and power on the node.'}

Step 3: {'Step': 'Cool down the CPU', 'Action': 'Power down the node, allow the CPU to cool down for 30 minutes, and then power on the node.'}

Post-Check Verification

```
show system status
show system alarms
show power supply status
```

```
show fan status  
show cpu temperature
```