

Ericsson Access Switch Node (Node ID: Ericsson-Access-Bangalore-KA-64) - Alarm Code: ALARM_6786 Resolving SOP

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_6786

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the Critical Alarm Code: ALARM_6786 on the Ericsson Access Switch Node (Node ID: Ericsson-Access-Bangalore-KA-64).

Potential Root Causes

Cause	Probability
Invalid or Misconfigured Network Interface	High
Faulty or Malfunctioning Network Interface Card (NIC)	Medium
Software or Firmware Issues	Low

Diagnostic Commands

```
show node info
show interface status
show network interface detail
show tech support | include ALARM_6786
```

Resolution Steps

- Step 1: {'Step': '1. Check the network interface configuration', 'Description': 'Verify that the network interface is properly configured. If not, correct the configuration.', 'CLI_Command': 'set network interface '}
- Step 2: {'Step': '2. Replace the faulty Network Interface Card (NIC)', 'Description': 'Replace the faulty NIC with a new one.', 'CLI_Command': 'replace network interface card '}
- Step 3: {'Step': '3. Update the software or firmware (if necessary)', 'Description': 'Update the software or firmware to the latest version if the issue is related to software or firmware issues.', 'CLI_Command': 'download software '}

Post-Check Verification

```
show node info
```

```
show interface status
show network interface detail
show tech support | include ALARM_6786
```