

Ericsson Access Switch Alarm SOP (ALARM_7767)

Node: Ericsson-Access-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_7767

Description

This SOP outlines the steps to diagnose and resolve a minor alarm (ALARM_7767) on the Ericsson Access Switch (Node ID: Ericsson-Access-Bangalore-KA-64).

Potential Root Causes

Cause	Probability
Incorrect Configuration	High
Hardware Failure	Medium
Software Issue	Low

Diagnostic Commands

```
show system status
show alarms
show interface status
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Check the system logs for any error messages', 'Action': 'show system logs'}
- Step 2: {'Step': '2. Verify the switch configuration', 'Action': 'show system configuration'}
- Step 3: {'Step': '3. Run a diagnostic test on the affected interface', 'Action': 'test interface '}
- Step 4: {'Step': '4. Reboot the switch if necessary', 'Action': 'reboot'}
- Step 5: {'Step': '5. Check for any software or firmware updates', 'Action': 'show system software version'}

Post-Check Verification

```
show system status
show alarms
show interface status
```