

Ericsson Access Switch Troubleshooting SOP

(ALARM_2133)

Node: Ericsson-Access-Bangalore-KA-80 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_2133

Description

ALARM_2133: Critical Alarm on Ericsson-Access-Bangalore-KA-80 Access Switch

Potential Root Causes

Cause	Probability
Hardware Failure: PSU (Power Supply Unit)	High
Software Bug: Access Switch Firmware	Medium
Configuration Issue: Wrong settings applied	Low

Diagnostic Commands

```
show alarm
show environment
show tech-support
show running-config
```

Resolution Steps

- Step 1: {'Step': 'Verify PSU status', 'Action': "Show PSU status using 'show environment' command"}
- Step 2: {'Step': 'Replace faulty PSU', 'Action': 'Swap PSU with new one and power cycle the switch'}
- Step 3: {'Step': 'Update Access Switch Firmware', 'Action': 'Backup current configuration, update firmware, and reboot the switch'}
- Step 4: {'Step': 'Re-apply correct configuration', 'Action': "Use 'copy running-config startup-config' command to save changes"}

Post-Check Verification

```
show alarm
show environment
show running-config
```