

Ericsson Access Switch Alarm SOP: ALARM_4464

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_4464

Description

This SOP outlines the steps to diagnose and resolve a Major alarm (ALARM_4464) on Ericsson Access Switch (Node ID: Ericsson-Access-Bangalore-KA-84).

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Configuration Mismatch	Low

Diagnostic Commands

```
show alarm history
show system status
show interface status
show log messages | include ALARM_4464
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the affected node', 'Action': "Enter the command 'power-cycle node' to restart the node."}
- Step 2: {'Step': '2. Check and update the software', 'Action': "Enter the command 'show version' to check the software version and update if necessary."}
- Step 3: {'Step': '3. Verify interface connections', 'Action': "Enter the command 'show interface status' to verify if all interfaces are connected properly."}
- Step 4: {'Step': '4. Reconfigure the node if necessary', 'Action': "Enter the command 'configure' to access the configuration mode and reconfigure the node if necessary."}

Post-Check Verification

```
show system status
show interface status
show log messages | include ALARM_4464
```