

Ericsson Access Switch - ALARM_6609 - Warning

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6609

Description

ALARM_6609 is a warning alarm indicating a possible issue with the Access Switch in Bangalore KA-84. This alarm may be triggered by various root causes.

Potential Root Causes

Cause	Probability
High CPU utilization	High
Interface congestion	Medium
Software bug	Low

Diagnostic Commands

```
show cpu utilization
show interfaces
show system status
show software version
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization', 'Action': "Run 'show cpu utilization' command"}
- Step 2: {'Step': 'Check interface congestion', 'Action': "Run 'show interfaces' command"}
- Step 3: {'Step': 'Check software version', 'Action': "Run 'show software version' command"}
- Step 4: {'Step': 'Restart the access switch', 'Action': "run 'reboot system' command"}
- Step 5: {'Step': 'Update software if required', 'Action': "run 'software update' command"}

Post-Check Verification

```
show cpu utilization
show interfaces
show system status
```