

# Ericsson Access Switch - Major Alarm ALARM\_3243 SOP

**Node:** Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM\_3243

## Description

This SOP outlines the steps to diagnose and resolve a Major alarm ALARM\_3243 on the Ericsson Access Switch node Ericsson-Access-Chennai-TN-92.

## Potential Root Causes

| Cause                               | Probability |
|-------------------------------------|-------------|
| Hardware failure in the switch card | High        |
| Software bug in the switch firmware | Medium      |
| Configuration issue with the switch | Low         |

## Diagnostic Commands

```
show tech-support
show alarm-history
show switch-card status
```

## Resolution Steps

- Step 1: {'Step': '1. Power cycle the switch', 'Action': "Use the 'power-cycle' command to reboot the switch."}
- Step 2: {'Step': '2. Check for hardware failure', 'Action': "Use the 'show switch-card status' command to verify the status of the switch card. If the card is faulty, replace it with a spare card."}
- Step 3: {'Step': '3. Check for software bug', 'Action': "Use the 'show software-version' command to verify the firmware version of the switch. If the firmware is outdated, upgrade to the latest version."}
- Step 4: {'Step': '4. Check for configuration issue', 'Action': "Use the 'show config' command to verify the configuration of the switch. If the configuration is incorrect, correct the issue and save the configuration."}

## Post-Check Verification

```
show alarm-history
show switch-card status
show software-version
```