

Ericsson Access Switch Alarm Resolution SOP for ALARM_2542

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2542

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the ALARM_2542 (Warning) on the Ericsson-Access-Delhi-NCR-14 access switch.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
show alarm detail ALARM_2542
show tech-support
show version
show running-config
```

Resolution Steps

- Step 1: {'Step': '1. Check system logs for any relevant error messages.', 'Action': ''}
- Step 2: {'Step': '2. Verify the software version and apply any available patches.', 'Action': 'show version && apply patch'}
- Step 3: {'Step': '3. Check the configuration for any inconsistencies.', 'Action': 'show running-config && verify config'}
- Step 4: {'Step': '4. Perform a hardware check.', 'Action': 'check hardware status'}
- Step 5: {'Step': '5. If none of the above steps resolve the issue, contact Ericsson support.', 'Action': ''}

Post-Check Verification

```
show alarm detail ALARM_2542 && verify alarm status
show version && verify software version
show running-config && verify config
```

```
show tech-support && verify system logs
```