

Alarm Resolution SOP for Ericsson Access Switch Delhi NCR-14

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5442

Description

ALARM_5442: Critical Alarm on Ericsson Access Switch Delhi NCR-14

Potential Root Causes

Cause	Probability
High CPU Utilization due to software defects	High
Hardware failure in the switch	Medium
Insufficient memory or disk space	Low

Diagnostic Commands

```
show cpu utilization
show memory utilization
show disk space
show interface status
show alarm history
```

Resolution Steps

- Step 1: {'Step': 'Restart the switch to clear the issue', 'CLI_Command': 'switchover'}
- Step 2: {'Step': 'Upgrade the software to the latest version', 'CLI_Command': 'upgrade software'}
- Step 3: {'Step': 'Replace the faulty hardware component', 'CLI_Command': 'replace hardware'}
- Step 4: {'Step': 'Monitor the CPU, memory, and disk space usage', 'CLI_Command': 'show cpu utilization, show memory utilization, show disk space'}
- Step 5: {'Step': 'Check the alarm history to identify the cause', 'CLI_Command': 'show alarm history'}

Post-Check Verification

```
show cpu utilization
show memory utilization
show disk space
```

```
show interface status  
show alarm history
```