

Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-14: ALARM_8995 Critical Alarm SOP

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_8995

Description

ALARM_8995: Critical alarm indicating a severe hardware or software issue on Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-14. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
show tech-support
show alarm-history
show hardware-status
show software-version
```

Resolution Steps

- Step 1: {'Step': 'Collect and analyze technical support data', 'Action': "Run 'show tech-support' command to collect technical support data."}
- Step 2: {'Step': 'Identify and replace faulty hardware', 'Action': "Use 'show hardware-status' command to identify faulty hardware. Replace the faulty hardware and use 'install ' command to install the new hardware."}
- Step 3: {'Step': 'Apply software patch or upgrade', 'Action': "Use 'show software-version' command to check the current software version. Apply the latest software patch or upgrade using 'install software' command."}
- Step 4: {'Step': 'Verify configuration', 'Action': "Use 'show configuration' command to verify that the configuration is correct."}

Post-Check Verification

```
show alarm-status  
show hardware-status  
show software-version  
show log
```