

Ericsson Access Switch - Alarm Resolution SOP for ALARM_2486

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2486

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve ALARM_2486, a warning severity alarm on Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
Invalid or corrupted configuration file	High
Network interface or physical layer issue	Medium
Software or firmware issue	Low

Diagnostic Commands

```
show system alarm
show interface [interface-name]
show version
show configuration
```

Resolution Steps

- Step 1: {'Step': '1. Check the system logs for any error messages related to ALARM_2486', 'Action': 'show system log'}
- Step 2: {'Step': '2. Verify the network interface and physical layer settings', 'Action': 'show interface [interface-name]', 'CLI_Command': 'configure terminal interface [interface-name] no shutdown'}
- Step 3: {'Step': '3. Reboot the node to clear any software or firmware issues', 'Action': 'reboot'}
- Step 4: {'Step': '4. Restore the configuration file from a backup', 'Action': 'configure terminal copy [backup-config-file] running-config'}

Post-Check Verification

```
show system alarm
show interface [interface-name]
show version
```

```
show configuration
```