

Ericsson Access Switch Alarm ALARM_3702

Handling Procedure

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_3702

Description

Handling procedure for Ericsson Access Switch Alarm ALARM_3702 (Severity: Warning) on Node Ericsson-Access-Delhi-NCR-28

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Insufficient memory or disk space	Medium
Misconfigured network protocols	Low

Diagnostic Commands

```
show cpu utilization
show memory statistics
show disk usage
show running-config | include network-protocols
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization and CPU-intensive processes', 'Action': 'show cpu utilization'}
- Step 2: {'Step': 'Verify memory and disk space availability', 'Action': 'show memory statistics, show disk usage'}
- Step 3: {'Step': 'Verify network protocol configurations', 'Action': 'show running-config | include network-protocols'}
- Step 4: {'Step': 'Clear CPU-intensive processes', 'Action': 'kill process-id'}
- Step 5: {'Step': 'Increase memory or disk space if necessary', 'Action': 'resize memory, resize disk'}
- Step 6: {'Step': 'Reconfigure network protocols if necessary', 'Action': 'configure network-protocols'}

Post-Check Verification

```
show cpu utilization
show memory statistics
```

```
show disk usage  
show running-config | include network-protocols
```