

Ericsson Access Switch ALARM_7809 SOP

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7809

Description

Major Alarm: ALARM_7809 on Ericsson Access Switch (Node ID: Ericsson-Access-Delhi-NCR-28) due to a critical system failure.

Potential Root Causes

Cause	Probability
Hardware Fault	High
Software Glitch	Medium
Environmental Factors	Low

Diagnostic Commands

```
show tech-support
show system status
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Check system logs for error messages', 'Action': 'show log system'}
- Step 2: {'Step': 'Verify hardware connections and cabling', 'Action': 'show interface status'}
- Step 3: {'Step': 'Reset the switch to factory defaults', 'Action': 'reset system to-default'}
- Step 4: {'Step': 'Upgrade software to latest version', 'Action': 'upgrade software'}

Post-Check Verification

```
show system status
show interface status
show tech-support
```