

Ericsson Access Switch Alarms - ALARM_9177 (Major)

Node: Ericsson-Access-Delhi-NCR-36 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9177

Description

Alarm ALARM_9177 indicates a major issue with the Ericsson Access Switch (Node ID: Ericsson-Access-Delhi-NCR-36). This alarm may be triggered due to hardware or software faults.

Potential Root Causes

Cause	Probability
Faulty hardware component (e.g., power supply unit)	High
Software configuration issue (e.g., incorrect settings)	Medium
Environmental factors (e.g., power outage, temperature fluctuations)	Low

Diagnostic Commands

```
show system resource status
show system alarm history
show hardware components status
show software version
```

Resolution Steps

- Step 1: {'Step': 'Check system logs for error messages', 'Action': 'show system log'}
- Step 2: {'Step': 'Verify hardware components status', 'Action': 'show hardware components status'}
- Step 3: {'Step': 'Check software configuration', 'Action': 'show software configuration'}
- Step 4: {'Step': 'Reset the switch to factory settings', 'Action': 'reset system to factory default'}

Post-Check Verification

```
show system resource status
show system alarm history
show hardware components status
show software version
```