

Standard Operating Procedure for Alarm Code ALARM_9369 on Ericsson Access Switch

Node: Ericsson-Access-Delhi-NCR-36 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9369

Description

Alarm Code ALARM_9369 is a Major alarm indicating a critical issue on Ericsson Access Switch Node Ericsson-Access-Delhi-NCR-36.

Potential Root Causes

Cause	Probability
Hardware failure in the node	High
Software bug in the node	Medium
Misconfigured settings on the node	Low

Diagnostic Commands

```
show tech-support
show alarm-history
show interfaces
```

Resolution Steps

Step 1: {'Step': 'Restart the node', 'Description': 'Restart the node to see if the alarm clears', 'Command': 'init restart'}

Step 2: {'Step': 'Check configuration', 'Description': 'Verify that all settings are configured correctly', 'Command': 'show configuration'}

Step 3: {'Step': 'Update firmware', 'Description': 'Ensure the node has the latest firmware', 'Command': 'firmware update'}

Post-Check Verification

```
show alarm-history
show interfaces
show tech-support
```