

Ericsson Access Switch ALARM_5748 Critical Alarm SOP

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5748

Description

This SOP outlines the steps to diagnose and resolve the ALARM_5748 Critical Alarm on the Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-118

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Hardware Failure	Medium
Software Bug	Low

Diagnostic Commands

```
show system resources cpu
show system resources memory
show system hardware status
show system software version
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': "Run 'show system resources cpu' command and verify if CPU utilization is above 90%", 'CLI_Command': 'show system resources cpu'}
- Step 2: {'Step': '2. Check for Hardware Failure', 'Action': "Run 'show system hardware status' command and verify if any hardware components are failing", 'CLI_Command': 'show system hardware status'}
- Step 3: {'Step': '3. Check for Software Bug', 'Action': "Run 'show system software version' command and verify if software is up-to-date", 'CLI_Command': 'show system software version'}
- Step 4: {'Step': '4. Restart the Switch', 'Action': "Run 'system restart' command to restart the switch", 'CLI_Command': 'system restart'}

Post-Check Verification

```
show system resources cpu
show system resources memory
```

```
show system hardware status  
show system software version
```