

Ericsson Access Switch ALARM_5971 SOP

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_5971

Description

ALARM_5971 - Major Alarm on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-118. This alarm indicates a critical system failure.

Potential Root Causes

Cause	Probability
Power Supply Unit (PSU) failure	High
Fan tray failure	Medium
Hardware module failure (e.g., line card, service card)	Low

Diagnostic Commands

```
show inventory
show environment
show power status
show fan status
show system resource usage
```

Resolution Steps

- Step 1: {'Step': 'Replace the faulty PSU', 'Action': 'Use the replacement PSU and replace the faulty one. Refer to the Ericsson hardware manual for instructions.'}
- Step 2: {'Step': 'Replace the faulty fan tray', 'Action': 'Use the replacement fan tray and replace the faulty one. Refer to the Ericsson hardware manual for instructions.'}
- Step 3: {'Step': 'Replace the faulty hardware module', 'Action': 'Use the replacement hardware module and replace the faulty one. Refer to the Ericsson hardware manual for instructions.'}

Post-Check Verification

```
show inventory
show environment
show power status
show fan status
```

```
show system resource usage
```