

Ericsson Access Switch Alarm SOP - ALARM_1254

Node: Ericsson-Access-Kolkata-WB-128 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_1254

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the Critical alarm ALARM_1254 on Ericsson Access Switch Node ID Ericsson-Access-Kolkata-WB-128.

Potential Root Causes

Cause	Probability
Hardware Fault	High
Software Issue	Medium
Configuration Error	Low

Diagnostic Commands

```
show system alarm
show system logs
show interface status
show system hardware
show system software
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the access switch', 'Description': 'Power off the access switch, wait for 30 seconds, and then power it back on.', 'CLI_Command': 'system shutdown now'}
- Step 2: {'Step': 'Check and replace faulty hardware', 'Description': 'Identify and replace any faulty hardware components.', 'CLI_Command': 'show system hardware'}
- Step 3: {'Step': 'Update software to latest version', 'Description': 'Update the access switch software to the latest version.', 'CLI_Command': 'install software version '}
- Step 4: {'Step': 'Verify configuration settings', 'Description': 'Verify that configuration settings are correct and consistent.', 'CLI_Command': 'show configuration'}

Post-Check Verification

```
show system alarm
show system logs
show interface status
```

```
show system hardware
```

```
show system software
```