

Ericsson Access Switch Alarm Handling SOP

(ALARM_5075)

Node: Ericsson-Access-Kolkata-WB-128 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_5075

Description

Handling Alarm Code ALARM_5075 on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-128

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Memory Leak	Medium
Interface Congestion	Low

Diagnostic Commands

```
show cpu stats
show memory stats
show interface stats
```

Resolution Steps

- Step 1: { 'Step': 'Check CPU Utilization', 'Action': 'Run show cpu stats command to check CPU utilization', 'CLI_Command': 'show cpu stats' }
- Step 2: { 'Step': 'Check Memory Utilization', 'Action': 'Run show memory stats command to check memory utilization', 'CLI_Command': 'show memory stats' }
- Step 3: { 'Step': 'Check Interface Congestion', 'Action': 'Run show interface stats command to check interface congestion', 'CLI_Command': 'show interface stats' }
- Step 4: { 'Step': 'Clear CPU Cache', 'Action': 'Run clear cpu-cache command to clear CPU cache', 'CLI_Command': 'clear cpu-cache' }
- Step 5: { 'Step': 'Stop Unnecessary Processes', 'Action': 'Stop any unnecessary processes to free up resources', 'CLI_Command': 'stop-process ' }

Post-Check Verification

```
show cpu stats
```

```
show memory stats  
show interface stats
```