

Ericsson Access Switch Alarm: ALARM_5529

Node: Ericsson-Access-Kolkata-WB-128 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5529

Description

Critical Alarm on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-128

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Configuration Error	Low

Diagnostic Commands

```
show system status
show interface status
show alarm history
show tech-support
```

Resolution Steps

Step 1: {'Step': '1. Check System Status', 'Action': 'Run show system status command to identify any hardware or software issues', 'Action CLI': 'show system status'}

Step 2: {'Step': '2. Verify Interface Status', 'Action': 'Run show interface status command to confirm interface status', 'Action CLI': 'show interface status'}

Step 3: {'Step': '3. Check Alarm History', 'Action': 'Run show alarm history command to identify any recent alarms', 'Action CLI': 'show alarm history'}

Step 4: {'Step': '4. Run Tech-Support', 'Action': 'Run show tech-support command to gather detailed system information', 'Action CLI': 'show tech-support'}

Step 5: {'Step': '5. Reboot Node (if necessary)', 'Action': 'Reboot the Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-128'}

Post-Check Verification

```
show system status
show interface status
```

show alarm history