

Ericsson Access Switch ALARM_7322 - Major Alarm Troubleshooting SOP

Node: Ericsson-Access-Kolkata-WB-128 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7322

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_7322 - Major Alarm on the Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-128

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Hardware failure in the switch	Medium
Misconfigured network settings	Low

Diagnostic Commands

```
show cpu-usage
show hardware
show running-configuration | include [ALARM_7322 related config]
```

Resolution Steps

- Step 1: {'Step': 'Collect system logs for the last 24 hours and review for any critical errors', 'Action': 'show logging system history'}
- Step 2: {'Step': 'Check CPU utilization and adjust if necessary', 'Action': 'show cpu-usage | include average'}
- Step 3: {'Step': 'Verify hardware integrity and replace if necessary', 'Action': 'show hardware | include [affected hardware]'}
- Step 4: {'Step': 'Review and correct misconfigured network settings', 'Action': 'show running-configuration | include [ALARM_7322 related config]'}

Post-Check Verification

```
show cpu-usage | include average
show hardware | include [affected hardware]
show running-configuration | include [ALARM_7322 related config]
```