

# Ericsson PE Bangalore KA-59 Alarm Resolution SOP

**Node:** Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM\_3725

## Description

This SOP outlines the steps to resolve the ALARM\_3725 Critical alarm on the Ericsson Provider Edge Router located at Bangalore, KA-59.

## Potential Root Causes

| Cause                                 | Probability |
|---------------------------------------|-------------|
| High CPU Utilization on the PE Router | High        |
| Misconfiguration of the BGP Peer      | Medium      |
| Hardware Failure on the PE Router     | Low         |

## Diagnostic Commands

```
show cpu utilization
show bgp peers
show system resources
show tech-support
```

## Resolution Steps

Step 1: {'Step': 'Clear CPU Utilization Alarm', 'Action': "Use CLI command 'clear cpu-alarm' to clear the CPU Utilization alarm."}

Step 2: {'Step': 'Verify BGP Peer Configuration', 'Action': "Use CLI command 'show bgp peers' to verify the BGP peer configuration. Check for any misconfigurations and correct them if necessary."}

Step 3: {'Step': 'Replace Hardware (if necessary)', 'Action': 'If the root cause is determined to be a hardware failure, replace the faulty hardware component with a new one.'}

Step 4: {'Step': 'Restart the PE Router', 'Action': "Use CLI command 'restart pe-router' to restart the PE router."}

## Post-Check Verification

```
show cpu utilization
show bgp peers
show system resources
show alarm history
```