

Investigation and Resolution of ALARM_6553 on Ericsson Provider Edge Router

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_6553

Description

ALARM_6553 indicates a Major alarm on the Ericsson Provider Edge Router, indicating a potential issue with the control plane or data plane connectivity.

Potential Root Causes

Cause	Probability
High CPU Utilization on the RSP	High
Faulty Interface or Port on the RSP	Medium
Misconfigured Control Plane Protocol or Route Policy	Low

Diagnostic Commands

```
show process cpu
show interface status
show route protocols
show route policy
```

Resolution Steps

- Step 1: {'Step': 'Check CPU Utilization', 'Action': "Use 'show process cpu' to check the CPU utilization on the RSP, and adjust the threshold settings if necessary."}
- Step 2: {'Step': 'Verify Interface Status', 'Action': "Use 'show interface status' to verify the status of all interfaces, and perform a physical inspection of the interfaces if necessary."}
- Step 3: {'Step': 'Verify Control Plane Protocol', 'Action': "Use 'show route protocols' to verify the configuration of the control plane protocol, and adjust the settings if necessary."}
- Step 4: {'Step': 'Verify Route Policy', 'Action': "Use 'show route policy' to verify the configuration of the route policy, and adjust the settings if necessary."}
- Step 5: {'Step': 'Reset the RSP', 'Action': "Use 'reload' to reset the RSP, and verify the issue is resolved after the reboot."}

Post-Check Verification

```
show process cpu
show interface status
show route protocols
show route policy
```