

Ericsson Provider Edge Router (PE) Alarm SOP for ALARM_6071

Node: Ericsson-PE-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_6071

Description

ALARM_6071 is a Major alarm indicating a critical issue with the Provider Edge Router (PE) in Bangalore.

Potential Root Causes

Cause	Probability
High CPU usage on the PE router due to a software bug	High
Misconfigured Quality of Service (QoS) policy	Medium
Hardware failure on the PE router	Low

Diagnostic Commands

```
show system resources cpu usage
show policy qos
show hardware status
```

Resolution Steps

- Step 1: {'Step': 'Restart the PE router to clear the software bug', 'Actions': ['sudo shutdown -r now']}
- Step 2: {'Step': 'Reconfigure the QoS policy', 'Actions': ['configure', 'policy qos', 'set policy', 'exit']}
- Step 3: {'Step': 'Replace the faulty hardware component', 'Actions': ['replace hardware', 'insert new hardware']}

Post-Check Verification

```
show system resources cpu usage
show policy qos
show hardware status
```