

Standard Operating Procedure for Resolving Ericsson Provider Edge (PE) Bangalore KA-64 Alarm

ALARM_6944

Node: Ericsson-PE-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_6944

Description

This SOP outlines the steps to resolve the critical alarm ALARM_6944 on Ericsson Provider Edge (PE) Bangalore KA-64 node.

Potential Root Causes

Cause	Probability
Invalid or mismatched routing configuration	High
Hardware or software fault on the PE router	Medium
Network congestion or traffic overload	Low

Diagnostic Commands

```
show alarm summary
show alarm details ALARM_6944
show routing table
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Verify and correct routing configuration', 'Action': "Run command 'show routing table' and ensure there are no mismatches or invalid configurations. Correct any issues found."}
- Step 2: {'Step': 'Perform a hardware check', 'Action': "Run command 'show hardware status' to check for any hardware faults. Replace any faulty hardware components."}
- Step 3: {'Step': 'Clear the alarm', 'Action': "Run command 'clear alarm ALARM_6944' to clear the alarm. Monitor the network for any further issues."}

Post-Check Verification

```
show alarm summary
show alarm details ALARM_6944
show routing table
```

```
show interface status
```