

SOP for Resolving Major ALARM_7996 on Ericsson PE in Bangalore

Node: Ericsson-PE-Bangalore-KA-64 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7996

Description

This SOP outlines the steps to resolve the Major ALARM_7996 on Ericsson Provider Edge Router (PE) Node ID: Ericsson-PE-Bangalore-KA-64.

Potential Root Causes

Cause	Probability
High CPU Utilization due to excessive routing updates	High
Misconfigured BGP neighbor	Medium
Software or hardware issue with the PE router	Low

Diagnostic Commands

```
show cpu usage
show bgpsummary
show bgp neighbors
show ip bgp
show ip cef
show system resources
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Check CPU Utilization', 'Action': "Use the command 'show cpu usage' to check the CPU utilization of the PE router.", 'CLI_Command': 'show cpu usage'}
- Step 2: {'Step': 'Step 2: Verify BGP Configuration', 'Action': "Use the command 'show bgp neighbors' to verify the BGP configuration and neighbors.", 'CLI_Command': 'show bgp neighbors'}
- Step 3: {'Step': 'Step 3: Reset BGP Sessions', 'Action': "Use the command 'clear bgp *' to reset all BGP sessions.", 'CLI_Command': 'clear bgp *'}
- Step 4: {'Step': 'Step 4: Verify Routing Updates', 'Action': "Use the command 'show ip bgp' to verify the routing updates.", 'CLI_Command': 'show ip bgp'}
- Step 5: {'Step': 'Step 5: Contact Vendor Support', 'Action': 'Contact Ericsson support in case the issue persists after following the above steps.', 'CLI_Command': ''}

Post-Check Verification

```
show cpu usage
show bgpsummary
show bgp neighbors
show ip bgp
show ip cef
```