

Standard Operating Procedure for Major Alarm

ALARM_4387 on Ericsson Provider Edge Router

Ericsson-PE-Chennai-TN-83

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_4387

Description

ALARM_4387 is a major alarm indicating a critical issue with the Provider Edge Router. It requires immediate attention from the network engineer to prevent service outages and data loss.

Potential Root Causes

Cause	Probability
Invalid or misconfigured routing protocol parameters	High
Hardware failure or malfunction	Medium
Software corruption or faulty installation	Low

Diagnostic Commands

```
show routing protocols all
show ip bgp summary
show ip routing table
show hardware cpu
show hardware memory
```

Resolution Steps

- Step 1: {'Step': '1. Check routing protocol configuration', 'Action': "Verify routing protocol parameters using 'show routing protocols all' command"}
- Step 2: {'Step': '2. Verify BGP summary', 'Action': "Use 'show ip bgp summary' command to check BGP peerings and summary"}
- Step 3: {'Step': '3. Check routing table', 'Action': "Use 'show ip routing table' command to verify routing table consistency"}
- Step 4: {'Step': '4. Check hardware resources', 'Action': "Use 'show hardware cpu' and 'show hardware memory' commands to check CPU and memory usage"}
- Step 5: {'Step': '5. Troubleshoot hardware issues', 'Action': 'Replace faulty hardware components or consult Ericsson support for further assistance'}

Step 6: {'Step': '6. Reboot the router', 'Action': 'Reboot the router to clear any software corruption or reset default settings'}

Post-Check Verification

```
show routing protocols all
show ip bgp summary
show ip routing table
show hardware cpu
show hardware memory
```