

Standard Operating Procedure for Resolving ALARM_2615 on Ericsson PE Router

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2615

Description

ALARM_2615 indicates a Warning on the Ericsson Provider Edge Router, Node ID: Ericsson-PE-Delhi-NCR-23.

Potential Root Causes

Cause	Probability
Interface Down	High
Route Leaking	Medium
FEC (Forwarding Equivalence Class) Issue	Low

Diagnostic Commands

```
show interfaces brief
show ip bgp summary
show ip route
show ip bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 'Verify Interface Status', 'Action': 'Execute the command "show interfaces brief" to confirm the interface is down.'}
- Step 2: {'Step': 'Clear Route Leaking', 'Action': 'Execute the command "clear ip bgp *" to clear BGP sessions and redistribute routes.'}
- Step 3: {'Step': 'Verify FEC Status', 'Action': 'Execute the command "show ip bgp neighbors" to verify FEC status.'}
- Step 4: {'Step': 'Configure Interface', 'Action': 'Execute the command "interface " and "no shutdown" to enable the interface.'}

Post-Check Verification

```
show interfaces brief
show ip bgp neighbors
```

```
show ip route
```