

Ericsson Provider Edge Router SOP for Alarm Code ALARM_5294

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_5294

Description

ALARM_5294 is a Major alarm indicating a potential issue with the Provider Edge Router's routing protocol configuration.

Potential Root Causes

Cause	Probability
Invalid or corrupted routing protocol configuration	High
Failed software upgrade or patch installation	Medium
Hardware failure or malfunction	Low

Diagnostic Commands

```
show ip bgp summary
show bgp neighbors
show bgp routes
debug bgp
show log bgp
```

Resolution Steps

Step 1: {'Step': '1. Check the routing protocol configuration', 'Action': "Verify the routing protocol configuration using 'show ip bgp summary' and 'show bgp neighbors' commands.", 'Command': 'show ip bgp summary; show bgp neighbors'}

Step 2: {'Step': '2. Check for software upgrade or patch installation issues', 'Action': "Verify the software version using 'show version' command and check for any recent upgrades or patches.", 'Command': 'show version'}

Step 3: {'Step': '3. Check for hardware issues', 'Action': "Verify the hardware status using 'show hardware' command and check for any fault indicators.", 'Command': 'show hardware'}

Step 4: {'Step': '4. Reboot the router', 'Action': 'Reboot the router to clear any temporary issues.', 'Command': 'reload'}

Step 5: {'Step': '5. Verify the issue is resolved', 'Action': "Verify the routing protocol is stable and the issue is resolved using 'show ip bgp summary' and 'show bgp neighbors' commands.", 'Command': 'show ip bgp summary; show bgp neighbors'}

Post-Check Verification

```
show ip bgp summary
show bgp neighbors
show bgp routes
show log bgp
```